DEQ Laboratory and Environmental Assessment Division

Analytical Report

City of Sweet Home 1357 Pleasant Valley Rd Sweet Home, OR 97386 Reported: 8/3/2018 2:54:50PM

Project: Drinking Water Cyanotoxin Monitoring

Project Manager: Michael Mulvey

Sample Name: TINWSF-11736::SRC-AA

Sample Description: STREAM-SOUTH SANTIAM RIVER

Sampling Date: 31-Jul-18 08:07

Lab Number (Matrix): 1807257-01 (Source Water)

Sample Comments:

Cyanotoxin Compounds by Enzyme Linked Immunosorbent Assay

	Reporting			Rule Action	Vulnerable	People > age 6	Recreational
Analyte	Result	Limit	Units	Limit	People Limit	Limit	contact limit
Cylindrospermopsin	ND	0.11	μg/L	0.3	0.7	3	8
Preparation Date: 01-Aug-18 14:22		Analysis Date: 02-Aug-18 14:22					
Analyte Comme	ents: PV3::B						
Microcystins ADDA, Total	ND	0.30	μg/L	0.3	0.3	1.6	4
Preparation Date: 01-Aug-18 10:39		Analysis Date: 02-Aug-18 10:39		10:39			
Analyte Comme	ents: PV3::B						

Signed report on file, contact lab if required.

DEQ Laboratory and Environmental Assessment Division

Analytical Report

(Continued)

Qualifiers and Definitions

PV3::B Samples were received outside acceptable temperature range.

General Considerations

The analytical data contained in this report was generated to satisfy specific data quality objectives for the programs and projects under which they were generated. Users of the data must be able to understand potential limitations of the information and its suitability for their intended use. In cases where a portion of the sample analyses were analyzed by organizations other than DEQ, the review of this data was limited to information supplied by the non-DEQ organization. All quality control meets requirements unless otherwise noted. This report contains only sample data and the laboratory can supply quality control sample data upon request.

Page 2 of 3

Sampling Agency:_ Sample Collector (s): Marty Norris Facility Contact: Steven Haney Address: Facility: Oregon Department of Environmental Quality Chain of Custody Record ltem ¥es Yes Yes TINWSF-11736::SRC-AA TINWSF-23080::SRC-BA Relinquished By: City of Sweet Home - OR4100851 1357 Pleasant Valley Rd ठ Sweet Home SH073118-02) Cyn Cooler Contained Ice? Samples collected in the appropriate containers? All samples received within their holding times? Sample volumes sufficient for requested analyses? Samples received intact and without damage? Sample containers clearly and properly labeled? Sampled Same Day? TACIOLOS Sample ID OR 97386 . ځ` · Sweet Agency/Company TACCOS Sweet home Facility Phone: (541) 730-1845 **Applicable** Water Facility | Source or Finished | Sample Collection | State Code | wafer (Circle one) | Date and time Applicable Not Not MONE Sample Receipt Checklist *Office Use Only* 300 07/31/18 water (Circle one) Source Water Source Water 0307 Date/Time S ഗ Sample Information П П 81/18/18 Yes Date and time (080) DEQ Contact: Received By: Temperature Check (IR/Sample): 13,5 C Qtime: 4/6/57 COC form properly signed? Sample reservation checked at time of sample receipt? If yes were all samples properly preserved? STREAM-SOUTH SANTIAM RIVER IN FOSTER LAKE DAM Sample Receipt Comments 19450-Collection Address Michael Mulvey (if in Distribution) CARRE Agency/Company Dry 37 Survey: \ 人)氏圧大 Comments 8-1-18 Date/Time ŊÌ